

ColC

P18062.A40.DOC

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Inventor

: Stephen PALM

Certificate of Corrections Branch

Patent No.

: 6.950,459 Bi

Issued: September 27, 2005

Appl. No.

: 09/473,683

Filed: December 29, 1999

For

: ACTIVATION OF MULTIPLE XDSL MODEMS WITH HALF DUPLEX AND FULL DUPLEX PROCEDURES

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
U.S. Patent and Trademark Office
Customer Service Window
Randolph Building
401 Dulany Street
Alexandria, VA 22314

Certificate
MAR 2 0 2006
of Correction

Sir:

Please find attached a proposed Certificate of Correction.

Please correct the following errors appearing in the printed patent, which are the fault of the U.S. Patent and Trademark Office, as per the attached Certificate of Correction. Since these errors are the fault of the U.S. Patent and Trademark Office, no fee is due.

On the cover of the printed patent, at Item (56), References Cited, the following Other Publication was omitted and should be included:

---ITU-T recommendation G.994 ("Handshake Procedures for Digital Subscriber Line (DSL) Transceivers"), published by the International Telecommunication Union in February, 2001;---

This reference appeared correctly on the initialed Form PTO-1449 considered by the Examiner in

P18062.A40.DOC

January, 2004, which was attached to the Office Action mailed March 11, 2004.

At column 20, line 23 (claim 1, line 2) of the printed patent, after "comprising" insert ---: This appeared correctly on page 2, line 7 of the Response Under 37 C.F.R. 1.112 filed August 16, 2004.

At column 20, line 34 (claim 1, line 14) of the printed patent, "system, the" should be ---of the first predetermined---. This appeared correctly on page 2, line 15 of the Response Under 37 C.F.R. 1.112 filed August 16, 2004.

At column 20, line 38 (claim 1, line 17) of the printed patent, "indication" should be --- indicating---. This appeared correctly on page 3, line 1 of the Response Under 37 C.F.R. 1.112 filed August 16, 2004.

At column 20, line 52 (claim 3, line 1) of the printed patent, after "wherein" insert ---the---. This appeared correctly on page 3, line 11 of the Response Under 37 C.F.R. 1.112 filed August 16, 2004.

At column 21, line 5 (claim 8, line 2) of the printed patent, "transmits" should be --- transmit---. This appeared correctly on page 4, line 12 of the Response Under 37 C.F.R. 1.112 filed August 16, 2004.

Therefore, it is respectfully requested that a Certificate of Correction issue in the aboveidentified patent as follows:

On the cover of the printed patent, at Item (56), References Cited, the following Other Publication was omitted and should be included:

---ITU-T recommendation G.994 ("Handshake Procedures for Digital Subscriber Line

P18062.A40.DOC

(DSL) Transceivers"), published by the International Telecommunication Union in February,

2001;---

At column 20, line 23 (claim 1, line 2) of the printed patent, after "comprising"

insert ---: ---.

At column 20, line 34 (claim 1, line 14) of the printed patent, "system, the" should be ---

of the first predetermined---.

At column 20, line 38 (claim 1, line 17) of the printed patent, "indication" should be ---

indicating---.

At column 20, line 52 (claim 3, line 1) of the printed patent, after "wherein" insert

---the---.

At column 21, line 5 (claim 8, line 12) of the printed patent, "transmits" should be

---transmit---.

Should there be any questions, the Examiner is invited to contact the undersigned at the

below-listed number.

Respectfully submitted,

Stephen PALM

Bruce H. Bernstein

Reg. No. 29,027

Steven Wegman

Reg. No. 31,438

February 14, 2006 GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191 (703) 716-1191 Approved for use through 04/30/2007, OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO.

: 6.950.459 B1

APPLICATION NO.: 09/473,683

ISSUE DATE

: September 27, 2005

INVENTOR(S)

: S. PALM

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, the following Other Publication was omitted and should be included:

--ITU-T recommendation G.994 ("Handshake Procedures for Digital Subscriber Line (DSL) Transceivers"), published by the International Telecommunication Union in February, 2001;---

At column 20, line 23 (claim 1, line 2) of the printed patent, after "comprising" insert ---: ---:

At column 20, line 34 (claim 1, line 14) of the printed patent, "system, the" should be ---of the first predetermined---.

At column 20, line 38 (claim 1, line 17) of the printed patent, "indication" should be ---indicating---.

At column 20, line 52 (claim 3, line 1) of the printed patent, after "wherein" insert ---the---.

At column 21, line 5 (claim 8, line 12) of the printed patent, "transmits" should be ---transmit---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C.

1950 Roland Clarke Place

Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.

PTO/SB/44 (04-05)
Approved for use through 04/30/2007. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Page __1_ of __1_

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 6,950,459 (5)

APPLICATION NO.: 09/473,683

ISSUE DATE : September 27, 2005

INVENTOR(S) :

: S. PALM

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the cover of the printed patent, at Item (56), References Cited, the following Other Publication was omitted and should be included:

—ITU-T recommendation G.994 ("Handshake Procedures for Digital Subscriber Line (DSL) Transceivers"), published by the International Telecommunication Union in February, 2001;---

At column 20, line 23 (claim 1, line 2) of the printed patent, after "comprising" insert ---: ---:

At column 20, line 34 (claim 1, line 14) of the printed patent, "system, the" should be ---of the first predetermined---.

At column 20, line 38 (claim 1, line 17) of the printed patent, "indication" should be ---indicating---.

At column 20, line 52 (claim 3, line 1) of the printed patent, after "wherein" insert ---the---.

At column 21, line 5 (claim 8, line 12) of the printed patent, "transmits" should be ---transmit---.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

GREENBLUM & BERNSTEIN, P.L.C. 1950 Roland Clarke Place Reston, VA 20191

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete to some and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.